# Wiping the AOPEN Chromebase Commercial Device

1. With the AOPEN Chromebase device in an powered OFF state, while pushing the RECOVERY button with a button tool, push the POWER button via another button tool at the other side of the Chromebase device to power ON the AOPEN Chromebase device.

2. Press 'ctrl + d' keys at the OS recovery screen to enter developer mode while seeing the screen to the left with a big yellow exclamation point .

3. Pushing the RECOVERY button again to turn off OS verification.

4. Press 'ctrl + d' keys again OR wait 10 seconds to start the reset process. The AOPEN Chromebase device is now resetting.

OS verification is OFF
Press SPACE to re-enable.

This should take 5-15 minutes. Wait until the AOPEN Chromebase device goes to the next screen.
Do not reboot the device during this process.

Preparing system for Developer Mode.
This may take a while.
Do not turn your computer off until it has restarted.

5. Press the spacebar to re-enable OS verification.

OS verification is OFF
Press SPACE to re-enable.

6. Press enter key to boot the AOPEN Chromebase device in normal mode.

OS verification is **ON**
Your system will reboot and local data will be cleared.

7. The AOPEN Chromebase device will now reboot and will display a welcome screen to set initial settings.

chrome

Welcome!

Select your language: English (United States)

Select your keyboard: US

Select a network   * No network

Accessibility   Continue